



RoHS

包装图



胶带 ADHESIVE TAPE

标签 LABEL

Note注解:

1. Place Housing into PE bag and seal PE bag. Label.
将 Housing放入PE 袋内，并将PE 袋封好.贴上标签.
2. Put PE bag packed products in cartons, Packing detail see the table below
将装好产品的PE 袋放入纸箱内，详细包装见下表
3. Label depends on customer request, carton opening joint with transparent tape
标签依客户要求而定，纸箱开口处用透明胶带贴合.
4. There shall be no dirt such as deformation phenomenon,
Mantissa box fillers must be used
每箱不可有脏污,变形现象,尾数箱必须用填充物
5. Carton material: K=K, Carton thickness: 6~7mm
纸箱材质:K=K, 纸箱厚度:6~7mm



Poles	Bag PCS	Box PCS
02	1000	19K
03	1000	13K
04	1000	9K
05	1000	8K
06	1000	7K
07	1000	6K
08	1000	6K
10	1000	4.5K
11	1000	4K
12	1000	3K
15	1000	1.5K

GENERAL TOLERANCE

.X ±0.30

.XX ±0.20

.XXX ±0.10

X.° ±0.2°

视角

GYA
Connectors东莞市国亚电子有限公司
Dong Guan Guo Ya Connectors co., Ltd.

APPROVAL

Yangzhengguo

CHECK

Yangjinyi

DRAWN

Lvtiansheng

DATE

2016/08/26

PART NO.

A2504HM-XXX


TITLE:

2.50mm Housing Packing

UNIT	SCALE	SHEET	REV	NUMBER
mm	1:1	1/1	A0	A-022


RoHS

包装图




PE 袋

Lable 标签



胶带ADHESIVE TAPE



标签LABEL

Note注解:

1. Place Housing into PE bag and seal PE bag. Label.
将 Housing放入PE 袋内, 并将PE 袋封好.贴上标签.
2. Put PE bag packed products in cartons, Packing detail see the table below
将装好产品的PE袋放入纸箱内, 详细包装见下表
3. Label depends on customer request, carton opening joint with transparent tape
标签依客户要求而定, 纸箱开口处用透明胶带贴合.
4. There shall be no dirt such as deformation phenomenon,
Mantissa box fillers must be used
每箱不可有脏污,变形现象,尾数箱必须用填充物
5. Carton material: K=K, Carton thickness: 6~7mm
纸箱材质:K=K, 纸箱厚度:6~7mm



Pdes	Bag PCS	Box PCS
02	1000	30K
03	1000	24K
04	1000	16K
05	1000	15K
06	1000	12K
08	1000	11K
09	1000	9K
10	1000	
11	1000	
12	1000	7K
13	1000	6K
14	1000	5K
15	1000	5K

GENERAL TOLERANCE

.X	±0.30
.XX	±0.20
.XXX	±0.10
X.°	±0.2°

GYA
Connectors东莞市国亚电子有限公司
Dong Guan Guo Ya Connectors co., Ltd.

APPROVAL

Yangzhengguo

CHECK

Yangjinyi

DRAWN

Lvtiansheng

DATE

2016/08/26

PART NO.
A2504H-XXXTITLE:
2.50mm Housing Packing

UNIT	SCALE	SHEET	REV	NUMBER
mm	1:1	1/1	A0	A-022

RoHS

包装图

Adhesive tape
胶带Eco-Label
环保标签

Note注解:

1.Quantity数量:

5K PCS/REEL 一卷5K/PCS

13 REEL/BOX 一箱13卷

65K PCS/BOX 一箱65K/PCS

2.Each reel and outer box must be labeled and
Eco-Label Respectively labeled

每盘和外箱都必须有标签及环保标签分别标示

3.Terminal winding direction as shown

端子缠绕方向如左图所示

4. There shall be no dirt such as deformation phenomenon,
Mantissa box fillers must be used

每箱不可有脏污,变形现象,尾数箱必须用填充物

5. Carton material: K=K, Carton thickness: 6~7mm

纸箱材质:K=K, 纸箱厚度:6~7mm

Tape over the terminal
纸带在端子下方卷装方式
Package way

Adhesive tape胶带

Label unified on the
box top right corner
外箱标签位于右上
角

GENERAL TOLERANCE

.X ± 0.30 .XX ± 0.20 .XXX ± 0.10 X° $\pm 0.2^{\circ}$ GYA
Connectors东莞市国亚电子有限公司
Dong Guan Guo Ya Connectors co., Ltd.

APPROVAL

Yangzhengguo

CHECK

Yangjinyi

DRAWN

Lvliansheng

DATE

2016/08/26

PART NO.

A2504T-XXX

TITLE:

2.50mm Terminal Packing

UNIT
mmSCALE
1:1SHEET
1/1REV
A0NUMBER
A-022

DATE

REV

ECN NO.

DESCRIPTION

MODIFY

APPROVAL

RoHS

包装图

Adhesive tape
胶带

Label

Eco-Label
环保标签

Note注解:

1.Quantity数量:

5K PCS/REEL 一卷5K/PCS

7 REEL/BOX 一箱7卷

35K PCS/BOX 一箱35K/PCS

2.Each reel and outer box must be labeled and
Eco-Label Respectively labeled

每盘和外箱都必须有标签及环保标签分别标示

3.Terminal winding direction as shown

端子缠绕方向如左图所示

4. There shall be no dirt such as deformation phenomenon,
Mantissa box fillers must be used

每箱不可有脏污,变形现象,尾数箱必须用填充物

5.Carton material: K=K, Carton thickness: 6~7mm

纸箱材质:K=K, 纸箱厚度:6~7mm

Tape over the terminal
纸带在端子上方卷装方式
Package way

Adhesive tape胶带

Label unified
on the box top
right corner
外箱标签位于
右上角

GENERAL TOLERANCE

.X ± 0.30 .XX ± 0.20 .XXX ± 0.10 X.° $\pm 0.2^{\circ}$

视角

视角

GYA
Connectors东莞市国亚电子有限公司
Dong Guan Guo Ya Connectors co., ltd.

PART NO.

A2504TM-XXX

TITLE:

2.50mm Terminal Packing

DATE

1

REV

2

ECN NO.

DESCRIPTION

3

MODIFY

4

APPROVAL

Yangzhengguo

Yangjinyi

Lvtiansheng

2016/08/26

UNIT
mmSCALE
1:1SHEET
1/1REV
A0NUMBER
A-022

8