





RoHS

包装图



胶带ADHESIVE TAPE



Note注解:

1. Place Housing into PE bag and seal PE bag. Label.
将 Housing放入PE 袋内, 并将PE 袋封好.贴上标签.
2. Put PE bag packed products in cartons, Packing detail see the table below
将装好产品的PE 袋放入纸箱内, 详细包装见下表
3. Label depends on customer request, carton opening joint with transparent tape
标签依客户要求而定, 纸箱开口处用透明胶带贴合.
4. There shall be no dirt such as deformation phenomenon,
Mantissa box fillers must be used
每箱不可有脏污,变形现象,尾数箱必须用填充物
5. Carton material: K=K, Carton thickness: 6~7mm
纸箱材质:K=K, 纸箱厚度:6~7mm





Poles	Bag PCS	Box PCS
02	1000	30K
03	1000	24K
04	1000	16K
05	1000	15K
06	1000	12K
08	1000	11K
09	1000	9K
10	1000	
11	1000	
12	1000	7K
13	1000	6K
14	1000	5K
15	1000	5K

A							GENERAL TOLERANCE	GYA Connectors 东莞市国亚电子有限公司 Dong Guan Guo Ya Connectors co., ltd.				PART NO.				
							.X ±0.30					A2506H-XXX				
							.XX ±0.20	APPROVAL CHECK DRAWN DATE				TITLE:				
							.XXX ±0.10					2.50mm Housing Packing				
							X.° ±0.2°									
	DATE	REV	ECN NO.	DESCRIPTION	MODIFY	APPROVAL	视 角	Yangzhengguo	Yangjinyi	Lvtiansheng	2016/08/26	UNIT	SCALE	SHEET	REV	NUMBER
	1		2	3	4	5	6	7	8		mm	1:1	1/1	A0	A-022	



纸箱材质:K=K, 纸箱厚度:6~7mm



Package way

						GENERAL TOLERANCE		GYA Connectors 东莞市国亚电子有限公司 Dong Guan Guo Ya Connectors co., Ltd.				PART NO. A2506T-XXX				
						.X ±0.30						TITLE: 2.50mm Terminal Packing				
						.XX ±0.20										
						.XXX ±0.10										
						X° ±0.2°	APPROVAL	CHECK	DRAWN	DATE	UNIT	SCALE	SHEET	REV	NUMBER	
DATE	REV	ECN NO.	DESCRIPTION	MODIFY	APPROVAL		Yangzhengguo	Yangjinyi	Lvtiansheng	2016/08/26	mm	1:1	1/1	A0	A-022	
1		2	3	4		5		6		7				8		